

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Mark E. EIDSON

GROUP ART UNIT : 2841

SERIAL NO.

09/964,736

EXAMINER

: Unassigned

FILED

September 28, 2001

FOR

METHOD AND SYSTEM FOR ATTACHING MULTIPLE CLOCKING

SOURCES TO AN SDRAM MEMORY ARRAY

ASSISTANT COMMISSIONER FOR PATENTS

Washington, D.C. 20231

ATTENTION: BOX MISSING PARTS

RESPONSE TO NOTICE OF INCOMPLETE REPLY **DATED DECEMBER 6, 2001**

SIR:

Enclosed herewith are the following:

(1) Substitute Drawings (2 sheets)

Please contact the undersigned if any questions remain with respect to the enclosed Notice. Applicants respectfully request issuance of a Filing Receipt.

Respectfully submitted,

Dated: January 23, 2002

William E. Curry

Reg. No. 43,572

KENYON & KENYON

1500 K Street, N.W., Suite 700

Washington, D.C. 20005

Tel.:

(202) 220-4200

Fax:

(202) 220-4201



United States Patent and Trademark Office

COMMISSIONER FOR PATENTS UNITED STATES PATENT AND TRADEMARK OFFICE Washington, D.C. 20231

www.uspto.gov

APPLICATION NUMBER 09/964,736

FILING/RECEIPT DATE

FIRST NAMED APPLICANT

ATTORNEY DOCKET NUMBER

& KENYON

HINGTON, DC 20005

ŠTREET, N.W., SUITE 700

09/28/2001

Mark E. Eidson

2207/11983

CONFIRMATION NO. 2175

FORMALITIES LETTER

OC000000007159000

Date Mailed: 12/06/2001

NOTICE OF INCOMPLETE REPLY (NONPROVISIONAL)

Filing Date Granted

The U.S. Patent and Trademark Office has received your reply on 11/29/2001 to the Notice to File Missing Parts (Notice) mailed 10/25/2001 and it has been entered into the nonprovisional application. The reply, however, does not include the following items required in the Notice. m

The period of reply remains as set forth in the Notice. You may, however, obtain EXTENSIONS OF TIME under the provisions of 37 CFR 1.136 (a) accompanied by the appropriate fee (37 CFR 1.17(a)).

A complete reply must be timely filed to prevent ABANDONMENT of the above-identified application.

The application is informal since it does not comply with the regulations for the reason(s) indicated below.

The required item(s) identified below must be timely submitted to avoid abandonment:

- Substitute drawings in compliance with 37 CFR 1.84 because:
 - drawing sheets do not have the appropriate margin(s) (see 37 CFR 1.84(g)). Each sheet must include a top margin of at least 2.5 cm. (1 inch), a left side margin of at least 2.5 cm. (1 inch), a right side margin of at least 1.5 cm. (5/8 inch), and a bottom margin of at least 1.0 cm. (3/8 inch);

A copy of this notice <u>MUST</u> be returned with the reply.

Customer Service Center

Initial Patent Examination Division (703) 308-1202

PART 2 - COPY TO BE RETURNED WITH RESPONSE